

| | | | | | | | | | | | | | | | | | |
|---|--|----------------|--|------------------------------|--|---|--|---------------------------------------|--|---------------------------------|--|---------------------------|--|-----------------------------|--|-----------------------|--|
| ENGINEERING CHANGE ORDER PREMIER AVIATION, INC 2621 AVIATION PARKWAY, GRAND PRAIRIE, TX 75052 FSCM - OSUV8 | | | | | | | | | | REQUESTED BY MANUFACTURING | | DATE OF CHANGE 2/13/98 | | ECO NO. 5407 ECO 5407 | | SHEET OF 1 1 | |
| FAA SUBMITTAL YES X NO | | | | STC(s) AFFECTED: SH8443SW | | | | | | APPROVALS | | | | | | | |
| | | | | | | | | | | PREPARED BY <i>Scott Kuyfus</i> | | DATE 2/13/98 | | | | | |
| REASON FOR CHANGE | | | | DOCUMENT AFFECTED | | | | | | CHECKED <i>D. Harbinger</i> | | DATE 2/13/98 | | | | | |
| FACILITATE FAB. | | | | DESIGN ERROR | | | | NUMBER B64-13022 | | REVISION IS WAS | | DATE 10/24/94 | | | | | |
| CUSTOMER CHANGE | | | | DRAFTING ERROR | | X | | | | | | | | | | | |
| DESIGN CHANGE | | | | ADDITION DESIGN INFO | | | | TITLE BLEED AIR ECU DETAILS / ASSY | | QUALITY <i>15th</i> | | DATE 2/13/98 | | | | | |
| OTHER | | | | | | | | | | MANUF <i>C. Tomlin</i> | | DATE 2/13/98 | | | | | |
| TYPE | | CLASSIFICATION | | | | | | | | | | ENGINEERING <i>1020</i> | | DATE 2/13/98 | | | |
| INCORPORATED | | | | RECORD | | | | PMA MINOR | | X | | TSO MINOR | | | | | |
| UNINCORPORATED | | X | | STC | | X | | PMA MAJOR | | | | TSO MAJOR | | | | | |
| DESCRIPTION: <u>SHEET 9 ZONE 4D</u> <u>WAS</u> | | | | | | | | | | | | | | <u>IS</u> | | | |
| {———— 4.75 ————} | | | | | | | | | | | | | | {———— 4.65 ————} | | | |
| <u>SHEET 9 ZONE 3C</u> <u>WAS</u> | | | | | | | | | | | | | | <u>IS</u> | | | |
| {———— 6.15 ————} | | | | | | | | | | | | | | {———— 6.33 ————} | | | |